

# RB 300 - Case Histories



Contractor	Customer	Location	Description	Date
EncoAdvanced Engineered Polymers		Barcelona, Spain	Structural Coating	2018
Cape Industrial Services		UK	Structural Coating	2018
Corroless Eastern		UK	Structural Repair	2018
New Tech Distribution		France	Chemical Tank Lining	2018
Harris Pye Fabrication		South Wales, UK	Structural Coating	2018
Continvest		Bulgaria	Chemical Tank Lining	2018
New Tech Distribution		France	Concrete Structural Repair	2018
Corroless Eastern		UK	Structural Repair	2018
Corroless Eastern	British Sugar	UK	Structural Repair	2018
Harris Pye Fabrication		South Wales, UK	Structural Coating	2018
Corroless Eastern		UK	Structural Repair	2018
Cape Industrial Services		UK	Structural Coating	2018
Callidus Process Solutions		Wangara, Australia	Structural Repair	2018
US Marine & Industrial Pump Repair		West Yorkshire, UK	Pump Repair	2018
Till & Whitehead	EDF Energy Nuclear Generation	Heysham 2 Power Station	Structural Repair	2018

# RB 300 - Case Histories



Contractor	Customer	Location	Description	Date
Jerwin Coatings		Lanarkshire, Scotland	Internal Tank Lining	2018
LTH Baas		Mariner of the Seas	Internal Tank Lining	2018
Flow-Tech Advanced Coatings		Israel	Structural Coating	2018
Corroguard		Germany	Structural Coating	2018
New Tech Distribution		France	Structural Repair	2018
Cape Industrial Services	Ineos	UK	Structural Coating	2018
Corroless Eastern		UK	Structural Repair	2018
Corroguard		Germany	Structural Coating	2018
CSC Australia		Australia	Structural Repair	2018
New Tech Distribution		France	Structural Repair	2018
Welding Engineers		UK	Structural Coating	2018
New Tech Distribution		France	Structural Repair	2018
Callidus Process Solutions		Wangara, Australia	Structural Repair	2018
	Royal Caribbean	Explorer of the Seas	Structural Repair	2018
Jerwin Coatings		Lanarkshire, Scotland	Internal Tank Lining	2018

# RB 300 - Case Histories



Contractor	Customer	Location	Description	Date
Alcotec		Belgium	Structural Repair	2018
KamBAL Industrial Supply		Phillipines	Gold Refinery Flooring	2018
LTH Baas	Royal Caribbean	Mariner of the Seas	Process Tank Lining	2018
Callidus Process Solutions		Wangara, Australia	Structural Repair	2018
Welding Engineers		UK	Structural Coating	2018
Till & Whitehead	EDF Energy Nuclear Generation	Heysham 2 Power Station	Structural Repair	2018
	TUI Cruises	Tui Mein Schiff 5	Scrubber Bleed Off Tank Refurbishment	2018
EP Industrial & Commercial Painting		England	Structural Repair	2018
Flow-Tech Advanced Coatings		Israel	Structural Coating	2018
Callidus Process Solutions		Wangara, Australia	Structural Repair	2018
Corroless Eastern		UK	Structural Repair	2018
Resitech		UK	Chemical Tank Lining	2018
Eastern Coatings		UK	Chemical Tank Lining	2018
Till & Whitehead	EDF Energy Nuclear Generation	Dungeness B Power Station	Cooling Water System	2018

# RB 300 - Case Histories



Contractor	Customer	Location	Description	Date
Alcotec		Belgium	Structural Repair	2017
Florock UK		Herts, England	Chemical Lining	2017
Callidus Process Solutions		Wangara, Australia	Structural Repair	2017
CSC Australia		Australia	Structural Repair	2017
	Key Tankers AS	Key Breeze	Chemical Tank Lining	2017
Actavo		Grangemouth, Scotland	Structural Repair	2017
Alcotec		Belgium	Structural Repair	2017
Wood Group	Valero Energy	Pembroke Refinery	Structural Coating	2017
MIPC bvba		Belgium	Concrete Chemical Bund Lining	2017
MIPC bvba		Belgium	Structural Repair	2017
Corroless Eastern	British Sugar	UK	Structural Repair	2017
Actavo		Grangemouth, Scotland	Structural Repair	2017
Steadvale Air Systems		Glenrothes, Scotland	Internal Tank Lining	2017
Alcotec		Belgium	Structural Repair	2017
Harris Pye Fabrication		South Wales, UK	Structural Coating	2017

# RB 300 - Case Histories




Contractor	Customer	Location	Description	Date
Corroguard	Newark Sugar Factory	Newark, UK	Structural Coating	2017
Jerwin Coatings	Jerwin Coatings	Lanarkshire, Scotland	Internal Tank Lining	2017
Callidus Process Solutions		Wangara, Australia	Structural Coating	2017
Till & Whitehead	EDF Energy Nuclear Generation	Dungeness B Power Station	Cooling Water System	2017
Harris Pye Fabrication		South Wales, UK	Structural Coating	2017
Harris Pye Fabrication		South Wales, UK	Structural Coating	2017
Continvest		Bulgaria	Chemical Tank Lining	2017
Harris Pye Fabrication		South Wales, UK	Structural Coating	2017
Continvest		Bulgaria	Chemical Tank Lining	2017
CSC Australia		Australia	Chemical Tank Lining	2017
Welding Engineers		UK	Structural Coating	2017
Callidus Process Solutions		Wangara, Australia	Structural Coating	2017
	Seven Star Tankers	Turkey	Chemical Tank Lining	2017
New Tech Distribution		France	Structural Coating	2017
Corroless Eastern		UK	Structural Coating	2017

# RB 300 - Case Histories



Contractor	Customer	Location	Description	Date
Welding Engineers		UK	Structural Coating	2017
CSC (SEA)		MT Bunga Kelana 9	Structural Coating	2017
CSC (SEA)		Singapore	Structural Coating	2017
Fonship AS	Graypen Limited	MT Key Star	Chemical Tank Lining	2017
New Tech Distribution		France	Structural Repair	2017
Corroless Eastern		UK	Chemical Tank Lining	2017
Corroless Eastern		UK	Chemical Tank Lining	2017
Flow-Tech Advanced Coatings		Israel	Structural Coating	2017
Welding Engineers		UK	Structural Coating	2017
Till & Whitehead		UK	Structural Coating	2017
Corroless Eastern		UK	Structural Coating	2017
Vadero Shipmanagement		MT Kaprifol	Chemical Tank Lining	2017
Vadero Shipmanagement		MT Kaprifol	Chemical Tank Lining	2017
Corroless Eastern		UK	Structural Coating	2017
Weir Engineering Services		Alloa, Scotland	Internal Tank Lining	2017

# RB 300 - Case Histories



Contractor	Customer	Location	Description	Date
Weir Engineering Services		Alloa, Scotland	Internal Tank Lining	2017
New Tech Distribution		France	Structural Coating	2017
Harris Pye Fabrication		South Wales, UK	Structural Coating	2017
Callidus Process Solutions		Wangara, Australia	Structural Coating	2017
Callidus Process Solutions		Wangara, Australia	Concrete Repair	2017
Callidus Process Solutions		Wangara, Australia	Ceramic Structural Repair	2017
Welding Engineers		UK	Tank Lining	2017
Welding Engineers		UK	Tank Lining	2017
Till & Whitehead	EDF Energy Nuclear Generation	Heysham Power Station	Cooling Water System	2017
Flow-Tech Advanced Coatings		Israel	Chemical Tank Lining	2017
Prochem International		Ulsan, Korea	Internal Tank Lining	2017
Weir Engineering Services		Alloa, Scotland	Internal Tank Lining	2017
Weir Engineering Services		Alloa, Scotland	Internal Tank Lining	2017
Alcotec		Belgium	Structural Coating	2017
Weir Engineering Services		Alloa, Scotland	Internal Tank Lining	2017

# RB 300 - Case Histories



Contractor	Customer	Location	Description	Date
Coatings International Africa		Durban, South Africa	Chemical Tank Lining	2017
New Tech Distribution		France	Structural Coating	2017
	Seven Star Tankers	MT ICDAS-11	Chemical Tank Lining	2017
Flow-Tech Advanced Coatings		Israel	Chemical Tank Lining	2017
US Marine & Industrial Pump Repair		West Yorkshire, UK	Pump Repair	2017
Weir Engineering Services		Alloa, Scotland	Internal Tank Lining	2017
New Tech Distribution		France	Structural Coating	2017
Till & Whitehead	EDF Energy Nuclear Generation	Heysham Power Station	Cooling Water System	2017
Corroless Eastern	British Sugar	UK	Structural Coating	2017
Jerwin Coatings	Jerwin Coatings	Lanarkshire, Scotland	Internal Tank Lining	2016
New Tech Distribution		France	Chemical Tank Lining	2016
EncoAdvanced Engineered Polymers		Barcelona, Spain	Chemical Tank Lining	2016
New Tech Distribution		France	Chemical Tank Lining	2016
CSC (SEA)		Singapore	Structural Coating	2016
Florock UK		Herts, England	Chemical Lining	2016
Callidus Process Solutions		Wangara, Australia	Structural Coating	2016



# RB 300 - Case Histories



Contractor	Customer	Location	Description	Date
Wood Group		UK	Chemical Tank Lining	2016
Intermodal Container Surveyors		Prestwick, Scotland	Structural Coating	2016
Welding Engineers		UK	Tank Lining	2016
Flow-Tech Advanced Coatings		Israel	Tank Lining	2016
Alcotec		Belgium	Tank Lining	2016
New Tech Distribution		France	Chemical Tank Lining	2016
EP Industrial & Commercial Painting		England	Chemical Tank Lining	2016
Steadvale Air Systems		Glenrothes, Scotland	Internal Tank Lining	2016
KamBAL Industrial Supply		Phillipines	Chemical Tank Lining	2016
RPM Group	RPM Group	Kellington, UK	Chemical Tank Lining	2016
Wood Group	Valero Energy	UK	Chemical Tank Lining	2016
RPM Group	RPM Group	Kellington, UK	Chemical Tank Lining	2016
CSC Australia		Australia	Chemical Tank Lining	2016
Specialist Coatings (GB)		Ninfield, UK	Chemical Tank Lining	2016
Wood Group		UK	Chemical Tank Lining	2016
CTS Grangemouth		Grangemouth, Scotland	Chemical Tank Lining	2016

# RB 300 - Case Histories



Contractor	Customer	Location	Description	Date
Continvest		Bulgaria	Chemical Tank Lining	2016
Steadvale Air Systems		Glenrothes, Scotland	Internal Tank Lining	2016
New Tech Distribution		France	Tank Lining	2016
Actavo	Petroineos	Grangemouth, Scotland	Chemical Tank Lining	2016
Ferrous Protection		Saddleworth, England	Chemical Tank Lining	2016
Corroless Eastern	British Sugar	UK	Structural Coating	2016
RPM Group	RPM Group	Torness Power Station	Chemical Tank Lining	2016
New Tech Distribution		France	Tank Lining	2016
Torishima Service Solutions		Glasgow, Scotland	Internal Tank Lining	2016
Corroless Eastern		UK	Internal Tank Lining	2016
Till & Whitehead	EDF Energy Nuclear Generation	Morecambe, UK	Cooling Water System	2016
Coatings International Africa		Durban, South Africa	Chemical Tank Lining	2016
Callidus Process Solutions		Wangara, Australia	Chemical Tank Lining	2016
Ceramic Polymer		Germany	Internal Tank Lining	2016
EP Industrial & Commercial Painting		Ellesmere Port, England	Chemical Tank Lining	2016
Site Sealants		Stirling, Scotland	Chemical Tank Lining	2016

# RB 300 - Case Histories



Contractor	Customer	Location	Description	Date
Corroless Eastern		UK	Chemical Storage Tank Lining	2016
Weir Engineering Services		Alloa, Scotland	Internal Tank Lining	2016
Corroless Eastern		UK	Chemical Storage Tank Lining	2016
CSC (SEA)		Singapore	Chemical Tank Lining	2016
Corroless Eastern		UK	Chemical Storage Tank Lining	2016
Corroless Eastern		UK	Chemical Storage Tank Lining	2016
New Tech Distribution		France	Tank Lining	2016
Corroless Eastern		UK	Chemical Storage Tank Lining	2016
Florock UK		Herts, England	Chemical Lining	2016
New Tech Distribution		France	Chemical Tank Lining	2016
Torishima Service Solutions		Glasgow, Scotland	Tank Lining	2016
EncoAdvanced Engineered Polymers		Barcelona, Spain	Chemical Tank Lining	2016
Corroless Eastern		UK	Chemical Tank Lining	2016
	Key Tankers AS	Key Breeze	Chemical Tank Lining	2016

# RB 300 - Case Histories



Contractor	Customer	Location	Description	Date
Actavo		Grangemouth, Scotland	Chemical Tank Lining	2016
New Tech Distribution		France	Chemical Tank Lining	2016
Florock UK		Herts, England	Chemical Lining	2016
Jerwin Coatings	Jerwin Coatings	Lanarkshire, Scotland	Internal Tank Lining	2016
Specialist Coatings (GB)		Ninfield, UK	Chemical Tank Lining	2016
New Tech Distribution		France	High Temperature Tank Lining	2016
Flow-Tech Advanced Coatings		Israel	Tank Lining	2016
Flow-Tech Advanced Coatings		Israel	Tank Lining (Ceramic Finish)	2016
Flow-Tech Advanced Coatings		Israel	Tank Lining (Laminating Grade)	2016
Corroless Eastern		UK	Tank Lining	2016
Torishima Service Solutions		Glasgow, Scotland	Tank Lining	2016
CSC Australia		Australia	Tank Lining	2016
Stork Technical Services	Stork Technical Services	Clyde Platform	Tank Lining	2016
Alcotec		Belgium	Tank Lining	2016
Corroless Eastern		UK	Tank Lining	2016
Jerwin Coatings	Jerwin Coatings	Lanarkshire, Scotland	Internal Tank Lining	2016
Weir Engineering Services		Alloa, Scotland	Internal Tank Lining	2016

# RB 300 - Case Histories




Contractor	Customer	Location	Description	Date
US Marine & Industrial Pump Repair		UK	Pump and valve refurbishment	2016
Till & Whitehead	EDF Energy Nuclear Generation	Morecambe, UK	Cooling Water System	2016
Corroless Eastern		UK	Internal Tank Lining	2016
V. Ships UK	Key Shipping	MV Key Bora	Cargo Tank Coating	2016
Corroless Eastern		UK	Internal Tank Lining	2016
Corroless Eastern		UK	Internal Tank Lining	2016
Actavo		Grangemouth, Scotland	Internal Tank Lining	2016
Jerwin Coatings	Jerwin Coatings	Lanarkshire, Scotland	Internal Tank Lining	2016
Clifton Rubber		Cambridgeshire, UK	Internal Tank Lining	2016
New Tech Distribution		France	Internal Tank Lining	2016
Steadvale Air Systems		Glenrothes, Scotland	Internal Tank Lining	2016
Deborah Services		Grangemouth, Scotland	Internal Tank Lining	2015
Florock UK		UK	Tank Lining	2015
Weir Engineering Services		Alloa, Scotland	Tank Internals (Topcoat)	2015
Deborah Services		Grangemouth, Scotland	Internal Tank Lining	2015

# RB 300 - Case Histories



Contractor	Customer	Location	Description	Date
Steadvale Air Systems		Glenrothes, Scotland	Internal Tank Lining	2015
Weir Engineering Services	Weir Minerals	Australia	Internal Tank Lining	2015
Specialist Coatings (GB)		Ninfield, UK	Internal Tank Lining	2015
Deborah Services		Grangemouth, Scotland	Internal Tank Lining	2015
Site Sealants		Scotland	Internal Tank Lining	2015
Corroless Eastern		UK	Internal Tank Lining	2015
Corroless Eastern		UK	Internal Tank Lining	2015
Corroless Eastern		UK	Internal Tank Lining	2015
Callidus Process Solutions		Wangara, Australia	High Temperature Tank Lining	2015
Corroless Eastern		UK	Internal Tank Lining	2015
Alcotec		Belgium	Internal Tank Lining	2015
Corroless Eastern		UK	Internal Tank Lining	2015
Callidus Process Solutions		Wangara, Australia	Internal Tank Lining	2015
Alcotec		Belgium	Internal Tank Lining	2015

# RB 300 - Case Histories



Contractor	Customer	Location	Description	Date
Corroless Eastern		UK	Internal Tank Lining	2015
Continvest		Sofia, Bulgaria	Internal Tank Lining	2015
Corroguard	Bury St Edmunds Sugar Factory	West Midlands, UK	High Temperature Internal Tank Lining	2015
Callidus Process Solutions		Balcatta, Australia	Internal Tank Lining	2015
Corroless Eastern		UK	Internal Tank Lining	2015
Till & Whitehead	EDF Energy Nuclear Generation	Morecambe, UK	Cooling Water System	2015
Alcotec		Belgium	Internal Tank Lining	2015
Corroless Eastern	British Sugar	UK	Internal Tank Lining	2015
Jerwin Coatings	Jerwin Coatings	Lanarkshire, Scotland	Internal Tank Lining	2015
Flow-Tech Advanced Coatings		Israel	Tank Lining	2015
Steadvale Air Systems		Glenrothes, Scotland	Internal Lining (RB 300TF)	2015
Corroless Eastern		UK	Internal Tank Lining	2015
Till & Whitehead	EDF Energy Nuclear Generation	Morecambe, UK	Cooling Water System	2015
Corroless Eastern		UK	Internal Tank Lining	2015

# RB 300 - Case Histories



Contractor	Customer	Location	Description	Date
Jerwin Coatings	Jerwin Coatings	Lanarkshire, Scotland	Internal Tank Lining	2015
Corroless Eastern		UK	Internal Tank Lining	2015
Corroless Eastern		UK	Internal Tank Lining	2015
KUE Group		Yorkshire, UK	Internal Tank Lining	2015
Specialist Coatings (GB)		Ninfield, UK	Internal Tank Lining	2015
Alcotec		Belgium	Internal Tank Lining	2015
Corroless Eastern		UK	Internal Tank Lining	2015
Corroless Eastern		UK	Internal Tank Lining	2015
Till & Whitehead	EDF Energy Nuclear Generation	Morecambe, UK	Internal Lining	2015
Wardle (Painters)	Valero Energy	Pembroke Refinery	Internal Tank Lining	2015
CSC (SEA)	PUB	Singapore	Reinforced Fibreglass Plastic Covers	2015
Wood Group	Wood Group	Angus, UK	Internal Tank Lining	2015
Jerwin Coatings	Jerwin Coatings	Lanarkshire, Scotland	Internal Tank Lining	2015
Corroless Eastern		UK	Internal Tank Lining	2015
New Tech Distribution		France	Internal Lining	2015



# RB 300 - Case Histories



Contractor	Customer	Location	Description	Date
Steadvale Air Systems		Glenrothes, Scotland	Internal Lining (RB 300TF)	2015
Till & Whitehead	EDF Energy Nuclear Generation	Morecambe, UK	Internal Lining	2015
Ceramic Polymer		Germany	Internal Coating	2015
Torishima Service Solutions	Torishima Service Solutions	Glasgow, Scotland	Internal Tank Lining	2015
Till & Whitehead	EDF Energy Nuclear Generation	Morecambe, UK	Internal Lining	2015
Alcotec		Belgium	Internal Tank Lining	2014
Jerwin Coatings		Lanarkshire, Scotland	Internal Lining	2014
Corroless Eastern		UK	Internal Tank Lining	2014
Flow-Tech Advanced Coatings		Israel	Internal Lining	2014
Steadvale Air Systems		Glenrothes, Scotland	Internal Lining (RB 300TF)	2014
Alcotec		Belgium	Internal Tank Lining	2014
Corroless Eastern		UK	Internal Tank Lining	2014
New Tech Distribution		France	Internal Tank Lining	2014
Wardle (Painters)	Valero Energy	Pembroke Refinery	Internal Tank Lining	2014
Wardle (Painters)	Valero Energy	Pembroke Refinery	Internal Tank Lining	2014
Wardle (Painters)	Valero Energy	Pembroke Refinery	Internal Tank Lining	2014
Cape Industrial Services		Aberdeen, Scotland	Internal Tank Lining	2014
Ceramic Polymer		Germany	Internal Coating	2014

# RB 300 - Case Histories



Contractor	Customer	Location	Description	Date
CSC Australia		Wollongong, Australia	Internal Lining	2014
Deborah Services	Deborah Services	Wakefield, UK	Tank Lining	2014
Specialist Coatings (GB)		Ninfield, UK	Tank internals	2014
Alcotec		Belgium	Internal Coating	2014
Alcotec		Belgium	Internal Tank Lining	2014
Corroless Eastern		Norfolk, UK	Internal Tank Coating	2014
Corroless Eastern	British Sugar	UK	Pipe and tank internals	2014
Weir Engineering Services	Siemens	Finland	Pipe and Tank Internals	2014
Torishima Service Solutions		Glasgow, Scotland	Internal Coating	2014
Corroless Eastern		UK	Internal Coating	2014
Weir Engineering Services	Siemens	Finland	Pipe and Tank Internals	2014
Torishima Service Solutions		UK	Internal coating	2014
Corroless Eastern		UK	Vessel - tank internals	2014
SPI Performance Coatings		UK	Internal coating	2014
CSC (SEA)		Singapore	Tank lining	2014
Corroless Eastern		UK	Internal Coating	2014
Alcotec		Belgium	Internal tank coating	2014
Ledwood Protective Coatings		UK	Internal coating	2014
Wood Group	Pyeroy	UK	Internal tank lining	2014
Ledwood Protective Coatings		UK	Internal coating	2014
Aqua Blast		UK	Internal coating	2014
CSC (SEA)		Singapore	Internal coating	2014

# RB 300 - Case Histories



Contractor	Customer	Location	Description	Date
CorroGuard	Stahler & Neuser	UK	Internal tank coating	2014
CorroGuard		UK	Internal tank coating	2014
Weir Engineering Services	Siemens	UK	Pipe and tank internals	2014
Weir Engineering Services		UK	Pipe work internals	2014
Weir Engineering Services	Clyde Union Pump	UK	Pump refurbishment	2014
US Marine & Industrial Pump Repair		UK	Pump and valve refurbishment	2014
Corroless Eastern		UK	Tank internals	2014
New Tech Distribution		France	Vessel - tank internals	2014
Wardle (Painters)	Valero Energy	UK	Tank lining	2014
GOA Enterprises		USA	Internal coating	2014
Corrosion Control Services		Australia	Internal coating	2014
Weir Engineering Services		UK	Pipe work internals	2014
Weir Engineering Services		UK	Pipe work internals	2014
Alcotec		Belgium	Internal tank coating	2014
Till & Whitehead	EDF Energy	UK	Tank lining	2014
Wardle (Painters)	Valero Energy	UK	Tank lining	2014
Alcotec		Belgium	Internal tank coating	2014
Corroless Eastern	British Sugar	UK	Pipe and tank internals	2014

# RB 300 - Case Histories



Contractor	Customer	Location	Description	Date
Corroless Eastern		UK	Internal tank lining	2013
CSC (SEA)		Singapore	Tank lining	2013
Wardle (Painters)	Valero Energy	UK	Tank lining	2013
Till & Whitehead	EDF Energy	UK	Vessel - tank internals	2013
Torishima Service Solutions	Torishima Service Solutions	UK	Pump refurbishment	2013
Weir Engineering Services		UK	Pipe work internals	2013
Wardle (Painters)	Valero Energy	UK	Tank lining	2013
Torishima Service Solutions	Torishima Service Solutions	UK	Pump refurbishment	2013
Wardle (Painters)	Valero Energy	UK	Tank lining	2013
Torishima Service Solutions	Torishima Service Solutions	UK	Pump refurbishment	2013
Torishima Service Solutions	Torishima Service Solutions	UK	Pump refurbishment	2013
KUE Group	EDF Energy	UK	Repair	2013
Till & Whitehead	EDF Energy	UK	Vessel - tank internals	2013
Deborah Services	Ineos	UK	Internal coating	2013
New Tech Distribution		France	Vessel - tank internals	2013
Torishima Service Solutions	Torishima Service Solutions	UK	Pump refurbishment	2013
Flow-Tech Chemicals		Israel	Internal coating	2013
US Marine & Industrial Pump Repair		UK	Pump coatings	2013
Torishima Service Solutions	Torishima Service Solutions	UK	Pump refurbishment	2013

# RB 300 - Case Histories




Contractor	Customer	Location	Description	Date
Steadvale Air Systems		UK	Compressor sump	2013
Torishima Service Solutions	Bilfinger Industrial Services	UK	Tank lining	2013
CSC (SEA)		Singapore		2013
Alcotec		Belgium	Internal tank lining	2013
Ceramic Polymer		Germany	Internal coating	2013
Wardle (Painters)	Chevron Texaco	UK	Internal tank lining	2013
US Marine & Industrial Pump Repair		UK	Pump & valve refurbishment	2013
Bilfinger Salmis UK	BP Exploration	UK	Bund coating	2013
Corroless Eastern	British Sugar	UK	Pipe and tank internals	2013
Corroless Eastern	British Sugar	UK	Pipe and tank internals	2013
Jerwin Coatings		UK	Vessel - tank internals	2013
Corroless Eastern	British Sugar	UK	Pipe and tank internals	2013
Wardle (Painters)	Chevron Texaco	UK	Internal tank lining	2013
Ceramic Polymer		Germany	Internal coating	2013
Wardle (Painters)	Chevron Texaco	UK	Internal tank lining	2013
Cape Industrial Services	BP Exploration	UK	Internal tank lining	2013
Till & Whitehead	EDF Energy	UK	Turbine repair	2013
Torishima Service Solutions	Torishima Service Solutions	UK	Internal coating	2013
Travis Perkins	Travis Perkins	UK	Bund coating	2013

# RB 300 - Case Histories



Contractor	Customer	Location	Description	Date
Travis Perkins	Travis Perkins	UK	Bund coating	2013
CorroGuard	British Sugar	UK	Internal tank lining	2013
Steadvale Air Systems		UK	Compressor sump	2013
Wardle (Painters)	Chevron Texaco	UK	Internal tank coating	2013
Till & Whitehead	EDF Energy	UK	Vessel - tank internals	2013
Weir Engineering Services	British Energy	UK	Pipe work internals	2013
Pyeroy		UK	Protective coating	2013
Pyeroy		UK	Internal coating	2013
Jerwin Coatings		UK	Vessel - tank internals	2013
Weir Engineering Services		UK	Pipe work internals	2013
Weir Engineering Services		UK	Pipe work internals	2013
Steadvale Air Systems		UK	Compressor sump	2013
Vadero Shipmanagement	Vadero Shipmanagement	Poland	Chemical tanker	2013
Jerwin Coatings		UK	Vessel - tank internals	2013
Deborah Services	BP Exploration	UK	Pipe work	2013
CorroGuard	British Sugar	UK	Laminating system	2013
Corroless Eastern	Nestle Fawdon	UK	Protective coating	2013

# RB 300 - Case Histories



Contractor	Customer	Location	Description	Date
Weir Engineering Services		UK	Pipe work internals	2013
Weir Engineering Services		UK	Pipe work internals	2013
Corroless Eastern	Sensient Colors	UK	Protective coating	2013
Corroless Eastern	British Sugar	UK	Internal tank coating	2013
Deborah Services	BP Exploration	UK	Pipe work	2013
Jerwin Coatings		UK	Vessel - tank internals	2013
Jerwin Coatings		UK	Vessel - tank internals	2013
Corroless Eastern	British Sugar	UK	Pipe and tank internals	2013
Jerwin Coatings		UK	Vessel - tank internals	2013
Novotech Industrial Service		Germany	Protective coating	2013
Weir Engineering Services	British Energy	UK	Internal pipe lining	2013
Weir Engineering Services		UK	Pipe work internals	2013
Cape Industrial Services	BP Exploration	UK	Internal tank lining	2012
Weir Engineering Services		UK	Pipe work internals	2012
Weir Engineering Services		UK	Pipe work internals	2012

# RB 300 - Case Histories



Contractor	Customer	Location	Description	Date
South Staffs Industries		uk	Protective coating	2012
Wardle (Painters)	Chevron Texaco	UK	Tank lining	2012
Wardle (Painters)	Chevron Texaco	UK	Tank lining repair	2012
Wardle (Painters)	Chevron Texaco	UK	Tank lining	2012
Flow-Tech Chemicals		Israel	Tank lining	2012
New Tech Distribution		France	Internal coating	2012
Wardle (Painters)	Chevron Texaco	UK	Tank lining	2012
Torishima Service Solutions	Torishima Service Solutions	UK	Pump refurbishment	2012
Torishima Service Solutions	Torishima Service Solutions	UK	Pump refurbishment	2012
Wardle (Painters)	Chevron Texaco	UK	Tank lining	2012
Torishima Service Solutions	Torishima Service Solutions	UK	Pump refurbishment	2012
Corroless Eastern		UK	Internal tank coating	2012
Hertel (UK)	BP Exploration	UK	Internal tank coating	2012
Weir Engineering Services		UK	Pipe work internals	2012
Weir Engineering Services		UK	Pipe work internals	2012
Weir Engineering Services		UK	Pipe work internals	2012
Orrmac Coatings		UK	Internal tank lining	2012
Orrmac Coatings		UK	Internal tank lining	2012



# RB 300 - Case Histories



Contractor	Customer	Location	Description	Date
Alcotec		Belgium	Internal coating	2012
Weir Engineering Services	British Energy	UK	Internal pipe lining	2012
Corroless Eastern	British Sugar	UK	Pipe and tank internals	2012
Corroless Eastern	British Sugar	UK	Pipe and tank internals	2012
Weir Engineering Services	Scottish Power	UK	Internal pipe lining	2012
Corroless Eastern	British Sugar	UK	Pipe and tank internals	2012
Corroless Eastern	British Sugar	UK	Pipe and tank internals	2012
New Tech Distribution		France	Internal coating	2012
CorroGuard	British Sugar	UK	Internal tank coating	2012
Flow-Tech Chemicals		Israel	Industrial flooring	2012
BIS Salamis	BP Exploration	UK	Internal coating	2012
Weir Engineering Services	British Energy	UK	Internal pipe lining	2012
Weir Engineering Services	British Energy	UK	Internal pipe lining	2012
CorroGuard	British Sugar	UK	Internal tank coating	2012
Weir Engineering Services	British Energy	UK	Internal pipe lining	2012
Flow-Tech Chemicals		Israel	Internal tank coating	2012

# RB 300 - Case Histories



Contractor	Customer	Location	Description	Date
Weir Engineering Services	Scottish Power	UK	Internal pipe lining	2012
Weir Engineering Services	Scottish Power	UK	Internal pipe lining	2012
Alcotec		Belgium	Tank lining	2012
Hyunwoo Union Trading Company		South Korea	Internal tank coating	2012
New Tech Distribution		France	Internal coating	2012
Jerwin Coatings		UK	Vessel - tank internals	2012
Weir Engineering Services	British Energy	UK	Internal pipe lining	2012
Weir Engineering Services	British Energy	UK	Internal pipe lining	2012
Weir Engineering Services	British Energy	UK	Internal pipe lining	2012
New Tech Distribution		France	Internal coating	2012
US Marine & Industrial Pump Repair		UK	Pump & valve repair	2012
Weir Engineering Services	British Energy	UK	Internal pipe lining	2012
Specialist Industrial Coatings		UK	Internal tank coating	2012
Austin Hayes		UK	Tank lining	2012
New Tech Distribution		France	Internal coating	2012
CorroGuard	British Sugar	UK	Process equipment refurbishment	2012
CEA Australia		Australia	Vessel - tank internals	2012

# RB 300 - Case Histories



Contractor	Customer	Location	Description	Date
CEA Australia		Australia	Vessel - tank internals	2012
CEA Australia		Australia	Vessel - tank internals	2011
Corroless Eastern		UK	Tank lining	2011
Austin Hayes		UK	Tank lining	2011
Wardle (Painters)	Valero Energy	UK	Tank lining	2011
Wardle (Painters)	Valero Energy	UK	Tank lining	2011
Flow-Tech Chemicals		USA	Tanks and structures	2011
New Tech Distribution		France	Vessel - tank internals	2011
New Tech Distribution		France	Vessel - tank internals	2011
BIS Salamis	BP Exploration	UK	Vessel - tank internals	2011
New Tech Distribution	Sotumec	France	Vessel - tank internals	2011
CEA Australia		Australia	Vessel - tank internals	2011
CEA Australia		Australia	Vessel - tank internals	2011
CEA Australia		Australia	Vessel - tank internals	2011
Corroless Eastern		UK	Metal repair	2011
Wardle (Painters)	Chevron Texaco	UK	Conductive lining	2011
BIS Industrial Services	BP Exploration	UK	Tank lining	2011
Corroless Eastern		UK	Tank repair	2011
Wardle (Painters)	Chevron Texaco	UK	Vessel lining	2011

# RB 300 - Case Histories



Contractor	Customer	Location	Description	Date
Alcotec		Belgium	Tank lining	2011
BIS Industrial Services	BP Exploration	UK	Tank repair	2011
Weir Engineering Services		UK	Structural coating	2011
BIS Industrial Services	BP Exploration	UK	Lining repair	2011
BIS Industrial Services	BP Exploration	UK	Lining repair	2011
New Tech Distribution		France	Vessel - tank internals	2011
New Tech Distribution		France	Vessel - tank internals	2011
Weir Engineering Services		UK	Structural coating	2011
Weir Engineering Services		UK	Structural coating	2011
Wardle (Painters)	Chevron Texaco	UK	Tank lining	2011
Weir Engineering Services	NPower	UK	Vessel - tank internals	2011
New Tech Distribution		France	Vessel - tank internals	2011
Corroless Eastern		UK	Internal tank repair	2011
Weir Engineering Services		UK	Tank internal	2011
Wardle (Painters)	Chevron Texaco	UK	Tank lining	2011
AW Environmental Solutions	Clean Tec Restoration	UK	Repair	2011
Weir Engineering Services	Scottish Power	UK	Internal coating	2011
CorroGuard	British Sugar	UK	Tank lining	2011
Weir Engineering Services		UK	Metal repair	2011
Corroless Eastern		UK	Tank internal	2011
Anticorrosion Control Services		UK	Tank lining	2011
CorroGuard	British Sugar	UK	Maintenance	2011

# RB 300 - Case Histories




Contractor	Customer	Location	Description	Date
Corroless Eastern	Evergreen Oil	UK	Tank lining	2011
Corroless Eastern		UK	Tank lining	2011
Corroless Eastern		UK	Tank lining	2011
Flow-Tech Chemicals		Israel	Tanks and structures	2011
US Marine & Industrial Pump Repair		UK	Pump & valve refurbishment	2011
US Marine & Industrial Pump Repair		UK	Pump & valve refurbishment	2011
Alcotec		Belgium	Maintenance	2011
Alcotec		Belgium	Maintenance	2011
Weir Engineering Services	Scottish Power	UK	Metal repair	2011
Hertel (UK)	BP Exploration	UK	Tank lining	2011
New Tech Distribution		France	Vessel - tank internals	2011
New Tech Distribution		France	Vessel - tank internals	2011
Alcotec		Belgium	Vessel - tank internals	2011
HCC Protective Coatings	Roquette (UK)	UK	Tank lining	2011
Weir Engineering Services		UK	Maintenance	2011
Weir Engineering Services		UK	Maintenance	2010
Weir Engineering Services		UK	Maintenance	2010
Weir Engineering Services		UK	Maintenance	2010
Weir Engineering Services		UK	Maintenance	2010
Weir Engineering Services		UK	Maintenance	2010
BIS Industrial Services	BP Exploration	UK	Structural coating	2010
Weir Engineering Services		UK	Maintenance	2010
Alcotec		Belgium	Maintenance	2010

# RB 300 - Case Histories



Contractor	Customer	Location	Description	Date
Weir Engineering Services		UK	Vessel - tank internals	2010
Weir Engineering Services		UK	Pump & valve refurbishment	2010
Weir Engineering Services		UK	Vessel - tank internals	2010
Hertel (UK)	BP Exploration	UK	Internal tank lining	2010
BIS Industrial Services	BP Exploration	UK	Sand filter vessel lining	2010
Corroless Eastern	British Sugar	UK	Internal vessel repair	2010
Alcotec		Belgium	Pump & valve repair	2010
Alcotec		Belgium	Pump & valve repair	2010
Wardle (Painters)	Chevron Texaco	UK	Internal vessel coating	2010
Weir Engineering Services		UK	Internal pipe lining	2010
BIS Industrial Services	BP Exploration	UK	Sand filter vessel lining	2010
Hertel (UK)	BP Exploration	UK	Internal tank lining	2010
New Tech Distribution	Metalblanc	France	Tank lining	2010
BIS Industrial Services	BP Exploration	UK	Sand filter vessel lining	2010
RBG	TOTAL	UK	Flange repair	2010
New Tech Distribution	Coresine	France	Vessel - tank internals	2010

# RB 300 - Case Histories



Contractor	Customer	Location	Description	Date
Alcotec		Belgium	Pump & valve repair	2010
Alcotec		Belgium	Pump & valve repair	2010
Weir Engineering Services		UK	Internal pipe lining	2010
New Tech Distribution	Valourec & Mannesman Tubes	France	Vessel - tank internals	2010
New Tech Distribution	Valourec & Mannesman Tubes	France	Vessel - tank internals	2010
Weir Engineering Services		UK	Internal pipe lining	2010
RBG	ConocoPhillips	UK	Vessel repair	2010
Corroless Eastern	British Sugar	UK	Internal tank repair	2010
Weir Engineering Services		UK	Pump & valve refurbishment	2010
Weir Engineering Services		UK	Pump & valve refurbishment	2010
PD Port Services	Fonship AS	Norway	Tank lining repair	2010
Corroless Eastern		UK	Vessel - tank internals	2010
Hertel (UK)	BP Exploration	UK	Internal tank coating	2010
Ceram-Kote		Germany	Tank lining	2010
Hertel (UK)	BP Exploration	UK	Internal tank coating	2010
Corroless Eastern		UK	Vessel - tank internals	2010

# RB 300 - Case Histories



Contractor	Customer	Location	Description	Date
Corroless Eastern	British Sugar	UK	Internal tank coating	2010
Corroless Eastern	British Sugar	UK	Internal tank coating	2010
New Tech Distribution	Textilose	France	Tank lining	2010
Alcotec		Belgium	Machine refurbishment	2010
Market SAS	Coresine	France	Tanks and structures	2010
Market SAS	Coresine	France	Vessel - tank internals	2010
RBG	TOTAL	UK	Flange repair	2010
Repair Protection & Maintenance		UK	Internal tank coating	2010
Weir Engineering Services		UK	Internal pipe work	2010
Weir Engineering Services		UK	Internal pipe work	2010
Hertel (UK)	North British Distillery	UK	Tank lining	2010
Flow-Tech Chemicals		Israel	Concrete floor	2010
Weir Engineering Services		UK	Internal pipe work	2010
Weir Engineering Services		UK	Internal pipe work	2010
Alcotec		Belgium	Machine refurbishment	2010
Alcotec		Belgium	Machine refurbishment	2010
ISG Jackson	Biggin Hill Library & Pool	UK	Tank coating	2010
RBG	TOTAL	UK	Flange repair	2010



# RB 300 - Case Histories



Contractor	Customer	Location	Description	Date
Weir Engineering Services		UK	Internal pipe work	2010
Weir Engineering Services		UK	Internal pipe work	2010
Hertel (UK)	BP Exploration	UK	Internal tank coating	2010
Weir Engineering Services		UK	Internal tank coating	2010
Finclean SKJ	Chevron Texaco	UK	Internal tank coating	2010
Hyunwoo Union Trading Company		Korea	Concrete and bund coating	2010
RBG	TOTAL	UK	Internal tank coating	2010
Finclean SKJ	Chevron Texaco	UK	Internal tank coating	2010
Alcotec		Belgium	Internal tank coating	2010
Alcotec		Belgium	Internal tank coating	2010
Weir Engineering Services		UK	Internal tank coating	2010
Weir Engineering Services		UK	Internal tank coating	2010
Alcotec		Belgium	Internal tank coating	2010
Weir Engineering Services		UK	Internal tank coating	2010
Weir Engineering Services		UK	Internal tank coating	2010

# RB 300 - Case Histories



Contractor	Customer	Location	Description	Date
RBG	TOTAL	UK	Internal tank coating	2009
Wardle (Painters)	Chevron Texaco	UK	Internal tank coating	2009
Wardle (Painters)	Chevron Texaco	UK	Internal tank coating	2009
Wardle (Painters)	Chevron Texaco	UK	Internal tank coating	2009
Weir Engineering Services		UK	Internal tank coating	2009
Alcotec		Belgium	Internal tank coating	2009
Wardle (Painters)	Chevron Texaco	UK	Internal tank coating	2009
Ceram-Kote		Germany	Tank lining	2009
Market SAS		France	Internal tank coating	2009
Market SAS		France	Internal tank coating	2009
Market SAS		France	Internal tank coating	2009
Weir Engineering Services		UK	Internal pipe work	2009
Hertel (UK)	BP Exploration	UK	Internal tank lining	2009
Weir Engineering Services		UK	Internal pipe work	2009
Hertel (UK)	BP Exploration	UK	Internal tank lining	2009

# RB 300 - Case Histories



Contractor	Customer	Location	Description	Date
Finclean SKJ	Chevron Texaco	UK	Vessel internal lining	2009
Finclean SKJ	Chevron Texaco	UK	Vessel internal lining	2009
Flow-Tech Chemicals		Israel	Concrete floor	2009
Flow-Tech Chemicals		Israel	Concrete floor	2009
Weir Engineering Services		UK	Internal pipe work	2009
Hertel (UK)	BP Exploration	UK	Internal tank lining	2009
Weir Engineering Services		UK	Internal pipe work	2009
Weir Engineering Services		UK	Internal pipe work	2009
Hertel (UK)	BP Exploration	UK	Internal tank lining	2009
Hertel (UK)	BP Exploration	UK	Internal tank lining	2009
Corroless Eastern	British Sugar	UK	Internal tank coating	2009
Weir Engineering Services		UK	Internal pipe work	2009
Weir Engineering Services		UK	Internal pipe work	2009
W & D Ross	Talisman Energy	UK	Internal tank lining - fuel tank	2009
W & D Ross	Talisman Energy	UK	Internal tank lining - fuel tank	2009
Weir Engineering Services		UK	Internal pipe work	2009

# RB 300 - Case Histories



Contractor	Customer	Location	Description	Date
W & D Ross	Talisman Energy	UK	Internal tank lining - fuel tank	2009
Steadvale Air Systems		UK	Compressor sump	2009
US Marine & Industrial Pump Repair		UK	Pump and valve refurbishment	2009
US Marine & Industrial Pump Repair		UK	Pump and valve refurbishment	2009
Weir Engineering Services		UK	Internal pipe work	2009
Weir Engineering Services		UK	Internal pipe work	2009
Hertel (UK)	BP Exploration	UK	Internal tank lining	2009
Flow-Tech Chemicals		Israel	Concrete floor	2009
RBG	Talisman Energy	UK	Internal tank coating	2009
Weir Engineering Services		UK	Internal pipe work	2009
Corroless Eastern	British Sugar	UK	Internal vessel coating	2009
Finclean SKJ	Chevron Texaco	UK	Vessel internal lining	2009
Philippe Lassarat		France	Tank lining	2009
Weir Engineering Services		UK	Internal pipe work	2009
Finclean SKJ	Chevron Texaco	UK	Vessel internal lining	2009
Market SAS		France	Internal tank coating	2009

# RB 300 - Case Histories




Contractor	Customer	Location	Description	Date
Alcotec		Belgium	Internal tank coating	2009
Finclean SKJ	Chevron Texaco	UK	Vessel internal lining	2009
Weir Engineering Services		UK	Internal pipe work	2009
BDS Contracts (Milford Haven)	Chevron Texaco	UK	Internal tank coating	2009
Jerwin Coatings		UK	Vessel - tank internals	2009
Weir Engineering Services		UK	Internal pipe work	2009
Clyde Corrosion		UK	Internal tank coating	2009
Alcotec		Belgium	Internal tank coating	2009
Weir Engineering Services		UK	Internal pipe work	2009
Alcotec		Belgium	Internal tank coating	2009
Alcotec		Belgium	Internal tank coating	2009
Flow-Tech Chemicals		Israel	Concrete floor	2009
Ceram-Kote		Germany	Tank lining	2009
Ceram-Kote		Germany	Tank lining	2009
Hertel (UK)	BP Exploration	UK	Internal tank lining	2009
Weir Engineering Services		UK	Internal pipe work	2009

# RB 300 - Case Histories



Contractor	Customer	Location	Description	Date
Weir Engineering Services		UK	Internal pipe work	2009
Weir Engineering Services		UK	Internal pipe work	2009
Weir Engineering Services		UK	Internal pipe work	2009
Weir Engineering Services		UK	Internal pipe work	2009
Weir Engineering Services		UK	Internal pipe work	2009
Weir Engineering Services		UK	Internal pipe work	2009
Alcotec		Belgium	Internal tank coating	2009
Weir Engineering Services		UK	Internal pipe work	2009
Alcotec		Belgium	Internal tank coating	2009
Alcotec		Belgium	Internal tank coating	2009
Alcotec		Belgium	Internal tank coating	2009
Weir Engineering Services		UK	Internal pipe work	2009
Finclean SKJ	Chevron Texaco	UK	Vessel internal lining	2009
Finclean SKJ	Chevron Texaco	UK	Vessel internal lining	2009
Weir Engineering Services		UK	Internal pipe work	2009

# RB 300 - Case Histories



Contractor	Customer	Location	Description	Date
Market SAS		France	Internal tank coating	2009
Weir Engineering Services		UK	Internal pipe work	2009
Weir Engineering Services		UK	Internal pipe work	2009
Weir Engineering Services		UK	Internal pipe work	2009
Market SAS		France	Internal tank coating	2009
Weir Engineering Services		UK	Internal pipe work	2008
Weir Engineering Services		UK	Internal pipe work	2008
Counter Corrosion		UK	Tank lining	2008
Weir Engineering Services		UK	Internal pipe work	2008
Market SAS		France	Internal tank coating	2008
Weir Engineering Services		UK	Internal pipe work	2008
Weir Engineering Services		UK	Internal pipe work	2008
Novotechnik		Germany	High temperature vessel lining	2008
Ceram-Kote		Germany	Tank lining	2008
Flow-Tech Chemicals		Israel	Concrete floor	2008
Alcotec		Belgium	Internal tank coating	2008

# RB 300 - Case Histories



Contractor	Customer	Location	Description	Date
Market SAS		France	Internal tank coating	2008
Market SAS		France	Internal tank coating	2008
Weir Engineering Services		UK	Internal pipe work	2008
BDS Contracts (Milford Haven)	Chevron Texaco	UK	Internal vessel lining	2008
Steadvale Air Systems		UK	Compressor sump	2008
Flow-Tech Chemicals		Israel	Tank lining	2008
Flow-Tech Chemicals		Israel	Tank lining	2008
Market SAS		France	Internal tank coating	2008
Weir Engineering Services		UK	Internal pipe work	2008
Weir Engineering Services		UK	Internal pipe work	2008
Alcotec		Belgium	Internal tank coating	2008
Steadvale Air Systems		UK	Compressor sump	2008
Wardle (Painters)	Chevron Texaco	UK	Internal vessel lining	2008
Wardle (Painters)	Chevron Texaco	UK	Internal vessel lining	2008
BDS Contracts (Milford Haven)	Chevron Texaco	UK	Internal vessel lining	2008
Market SAS		France	Internal tank coating	2008



# RB 300 - Case Histories



Contractor	Customer	Location	Description	Date
BDS Contracts (Milford Haven)	Chevron Texaco	UK	Internal vessel lining	2008
Weir Engineering Services		UK	Internal pipe work	2008
Weir Engineering Services		UK	Internal pipe work	2008
Weir Engineering Services		UK	Internal pipe work	2008
Uni-prep		UK	Tank lining	2008
Corroless Eastern	British Sugar	UK	Internal tank coating	2008
Weir Engineering Services		UK	Internal pipe work	2008
Market SAS		France	Internal tank coating	2008
Rotary Technical Services		Malaysia	Tank lining	2008
Weir Engineering Services		UK	Internal pipe work	2008
Weir Engineering Services		UK	Internal pipe work	2008
Weir Engineering Services		UK	Internal pipe work	2008
Market SAS		France	Internal tank coating	2008
Market SAS		France	Internal tank coating	2008
Weir Engineering Services		UK	Internal pipe work	2008
Weir Engineering Services		UK	Internal pipe work	2008

# RB 300 - Case Histories



Contractor	Customer	Location	Description	Date
Alcotec		Belgium	Internal tank coating	2008
Flow-Tech Chemicals		Israel	Tank lining	2008
Weir Engineering Services		UK	Internal pipe work	2008
Weir Engineering Services		UK	Internal pipe work	2008
HCC Protective Coatings		UK	Internal tank lining	2008
Weir Engineering Services		UK	Internal pipe work	2008
Weir Engineering Services		UK	Internal pipe work	2008
Wardle (Painters)	Chevron Texaco	UK	Internal vessel lining	2008
Weir Engineering Services		UK	Internal pipe work	2008
Weir Engineering Services		UK	Internal pipe work	2008
Weir Engineering Services		UK	Internal pipe work	2008
Weir Engineering Services		UK	Internal pipe work	2008
Weir Engineering Services		UK	Internal pipe work	2008
Weir Engineering Services		UK	Internal pipe work	2008
HCC Protective Coatings		UK	Internal tank lining	2008
Finclean SKJ	Chevron Texaco	UK	Internal tank coating	2008

# RB 300 - Case Histories



Contractor	Customer	Location	Description	Date
BDS Contracts (Milford Haven)	Chevron Texaco	UK	Internal vessel coating	2008
Market SAS		France	Internal tank coating	2008
Weir Engineering Services		UK	Internal pipe work	2008
Market SAS		France	Internal tank coating	2008
Market SAS		France	Internal tank coating	2008
Weir Engineering Services		UK	Internal pipe work	2008
Wardle (Painters)	Chevron Texaco	UK	Internal vessel lining	2008
Wardle (Painters)	Chevron Texaco	UK	Internal vessel lining	2008
Wardle (Painters)	Chevron Texaco	UK	Internal vessel lining	2008
Weir Engineering Services		UK	Internal pipe work	2008
Wardle (Painters)	Chevron Texaco	UK	Internal vessel lining	2008
Flow-Tech Chemicals		Israel	Tank lining	2008
Weir Engineering Services		UK	Internal pipe work	2008
Market SAS		France	Internal tank coating	2008
Wardle (Painters)	Chevron Texaco	UK	Internal vessel lining	2008

# RB 300 - Case Histories



Contractor	Customer	Location	Description	Date
Weir Engineering Services		UK	Internal pipe work	2008
US Marine & Industrial Pump Repair		UK	Pump and valve refurbishment	2008
Weir Engineering Services		UK	Internal pipe work	2008
Weir Engineering Services		UK	Internal pipe work	2008
Market SAS		France	Internal tank lining	2008
Weir Engineering Services		UK	Internal pipe work	2008
Weir Engineering Services		UK	Internal pipe work	2008
Weir Engineering Services		UK	Internal pipe work	2008
Weir Engineering Services		UK	Internal pipe work	2008
Weir Engineering Services		UK	Internal pipe work	2008
Weir Engineering Services		UK	Internal pipe work	2008
Weir Engineering Services		UK	Internal pipe work	2008
Weir Engineering Services		UK	Internal pipe work	2008
Steadvale Air Systems		UK	Air receiver application	2008
Alcotec		Belgium	Internal tank coating	2008
Weir Engineering Services		UK	Internal pipe work	2008

# RB 300 - Case Histories




Contractor	Customer	Location	Description	Date
Weir Engineering Services		UK	Internal pipe work	2008
W & D Ross	Talisman Energy	UK	Internal tank lining - fuel tank	2008
W & D Ross	Talisman Energy	UK	Internal tank lining - fuel tank	2008
Weir Engineering Services		UK	Internal pipe work	2008
Weir Engineering Services		UK	Internal pipe work	2008
Survair Coating Services		UK	Chemical bund in food processing plant	2008
Repair Protection & Maintenance		UK	Pipe and tank internals	2008
Weir Engineering Services	British Energy	UK	Internal pipe work	2008
Weir Engineering Services		UK	Internal pipe work	2007
Weir Engineering Services		UK	Internal pipe work	2007
Weir Engineering Services		UK	Internal pipe work	2007
Market SAS		France	Internal tank lining	2007
Market SAS		France	Internal tank lining	2007
Market SAS		France	Internal tank lining	2007

# RB 300 - Case Histories



Contractor	Customer	Location	Description	Date
Market SAS		France	Internal tank lining	2007
Market SAS		France	Internal tank lining	2007
Weir Engineering Services		UK	Internal pipe work	2007
Weir Engineering Services		UK	Internal pipe work	2007
Wardle (Painters)	Chevron Texaco	UK	Internal vessel lining	2007
Wardle (Painters)	Chevron Texaco	UK	Internal vessel lining	2007
Market SAS		France	Internal tank lining	2007
Weir Engineering Services		UK	Internal pipe work	2007
Market SAS		France	Internal tank lining	2007
TincQ Material Solutions	Corus	The Netherlands	Corus flourwashers repair	2007
Weir Engineering Services		UK	Internal pipe work	2007
Market SAS		France	Internal tank lining	2007
Weir Engineering Services		UK	Internal pipe work	2007
Market SAS		France	Internal tank coating	2007

# RB 300 - Case Histories



Contractor	Customer	Location	Description	Date
Weir Engineering Services		UK	Internal pipe work	2007
Market SAS		France	Internal tank lining	2007
Weir Engineering Services		UK	Internal pipe work	2007
Gemini Corrosion Services		UK	Internal vessel coating	2007
Gemini Corrosion Services		UK	Internal vessel coating	2007
Market SAS		France	Internal tank lining	2007
Weir Engineering Services		UK	Internal pipe work	2007
Weir Engineering Services		UK	Internal pipe work	2007
Weir Engineering Services		UK	Internal pipe work	2007
Poeton	Poeton	UK	Bund coating	2007
Weir Engineering Services		UK	Internal pipe work	2007
Sensata Technologies	Sensata Technologies	UK	Tank lining	2007
TincQ Material Solutions	Corus	The Netherlands	Tank lining	2007
Steadvale Air Systems		UK	Compressor sump	2007
Market SAS		France	Internal tank lining	2007
Market SAS		France	Internal tank lining	2007

# RB 300 - Case Histories



Contractor	Customer	Location	Description	Date
Gemini Corrosion Services		UK	Internal vessel coating	2007
US Marine & Industrial Pump Repair		UK	Pump and valve refurbishment	2007
TincQ Material Solutions	Corus	The Netherlands	Fluoride washer repair	2007
Chubu Electric Power Company	Chubu Electric Power Company	Japan	Vessel - tank internals	2007
Weir Engineering Services	British Energy	UK	Internal pipe work	2007
Materials Enhancement	British Sugar	UK	Internal vessel repair	2007
Wardle (Painters)		UK	Internal tank coating	2007
Weir Engineering Services		UK	Internal pipe work	2007
Repair Protection & Maintenance		UK	Internal pipe work	2007
Hertel (UK)	BP Exploration	UK	Internal repair for LP/HP oil spectrum	2007
Finclean SKJ	TOTAL	UK	Internal vessel coating	2007
Hertel (UK)	BP Exploration	UK	Internal tank coating - tank T804	2007
TincQ Material Solutions	Corus	The Netherlands	Tank lining	2007
Weir Engineering Services		UK	Internal pipe work	2007
Rotary Technical Services		Malaysia	Tank lining	2007



# RB 300 - Case Histories



Contractor	Customer	Location	Description	Date
Market SAS		France	Internal tank coating	2007
Market SAS		France	Internal tank coating	2007
Merkland Tanks		UK	Tank roof	2007
Weir Engineering Services		UK	Internal pipe work	2007
Materials Enhancement	British Sugar	UK	Internal tank lining	2007
Alcotec		Belgium	Internal tank coating	2007
Hertel (UK)	BP Exploration	UK	Pressure vessel - internal coating	2007
Market SAS		France	Internal tank coating	2007
TincQ Material Solutions	Corus	The Netherlands	Tank lining	2007
Market SAS		France	Internal tank coating	2007
Market SAS		France	Internal tank coating	2007
Finclean SKJ	Chevron Texaco	UK	Internal tank lining	2007
Market SAS		France	Internal tank coating	2007
Finclean SKJ	Chevron Texaco	UK	Internal vessel repair	2007
Market SAS		France	Internal tank coating	2007

# RB 300 - Case Histories



Contractor	Customer	Location	Description	Date
Market SAS		France	Internal tank coating	2007
Repair Protection & Maintenance		UK	Pipe and tank internals	2007
Weir Engineering Services	Magnox South	UK	Internal pipe lining	2007
Weir Engineering Services	Magnox South	UK	Internal pipe lining	2007
Weir Engineering Services	Magnox South	UK	Internal pipe lining	2007
Market SAS		France	Internal tank coating	2007
Wardle (Painters)	Chevron Texaco	UK	Vessel repair	2007
Market SAS		France	Internal tank coating	2007
Salamis	Talisman Energy	UK	Internal vessel coating	2007
Jerwin Coatings		UK	Vessel - tank internals	2007
Weir Engineering Services	Magnox South	UK	Internal pipe lining	2007
Steadvale Air Systems		UK	Compressor sump	2007
Engineering Industrial Services		UK	Chemical bund coating	2007
Weir Engineering Services	British Energy	UK	Internal pipe lining	2007
US Marine & Industrial Pump Repair		UK	Pump and valve refurbishment	2007

# RB 300 - Case Histories



Contractor	Customer	Location	Description	Date
US Marine & Industrial Pump Repair		UK	Pump and valve refurbishment	2007
Hertel (UK)	BP Exploration	UK	Internal tank floor coating	2007
Weir Engineering Services	British Energy	UK	Internal pipe lining	2007
Weir Engineering Services	British Energy	UK	Internal pipe lining	2007
Salamis		UK	Internal tank coating	2007
Weir Engineering Services	British Energy	UK	Internal pipe lining	2007
US Marine & Industrial Pump Repair		UK	Pump and valve refurbishment	2007
US Marine & Industrial Pump Repair		UK	Pump and valve refurbishment	2007
Weir Engineering Services	British Energy	UK	Internal pipe lining	2007
TincQ Material Solutions	Corus	The Netherlands	Tank lining	2007
Jerwin Coatings		UK	Vessel - tank internals	2007
GCG Shotblasting Services		UK	Internal vessel lining	2006
Market SAS		France	Internal tank coating	2006
Market SAS	Hanier Plaisance	France	Internal tank coating	2006
Fonship AS	Fonship AS	UK	Tank lining - food oils	2006

# RB 300 - Case Histories



Contractor	Customer	Location	Description	Date
Market SAS		France	Internal tank coating	2006
Finclean SKJ	Chevron Texaco	UK	Vessel repair	2006
Weir Engineering Services	British Energy	UK	Internal pipe lining	2006
Market SAS		France	Internal tank coating	2006
Weir Engineering Services		UK	Pipe work internals	2006
Weir Engineering Services		UK	Pipe work internals	2006
Weir Engineering Services		UK	Pipe work internals	2006
Repair Protection & Maintenance		UK	Pipe work internals	2006
BDS Contracts (Milford Haven)	Chevron Texaco	UK	Pipe work internals	2006
Wardle (Painters)	Chevron Texaco	UK	Internal vessel lining	2006
BDS Contracts (Milford Haven)	Chevron Texaco	UK	Internal vessel lining	2006
Finclean SKJ	Chevron Texaco	UK	Pipe work internals	2006
Wardle (Painters)	Chevron Texaco	UK	Pipe work internals	2006
Steadvale Air Systems		UK	Compressor sump	2006
Weir Engineering Services		UK	Pipe work internals	2006

# RB 300 - Case Histories




Contractor	Customer	Location	Description	Date
Hertel (UK)	BP Exploration	UK	Vessel internal lining	2006
Weir Engineering Services		UK	Pipe work internals	2006
Steadvale Air Systems		UK	Compressor sump	2006
Weir Engineering Services		UK	Pipe work internals	2006
Hertel (UK)	BP Exploration	UK	Vessel internal lining	2006
Hertel (UK)	BP Exploration	UK	Vessel internal lining	2006
RBG	Talisman Energy	UK	Vessel and pipe works	2006
Weir Engineering Services	EDF Energy	UK	Pipe work internals	2006
Market SAS		France	Internal tank lining	2006
Market SAS		France	Acid bund lining	2006
Repair Protection & Maintenance		UK	Pressure vessel	2006
Weir Engineering Services		UK	Pipe work internals	2006
US Marine & Industrial Pump Repair		Bahrain	Pump coatings	2006
US Marine & Industrial Pump Repair		Bahrain	Pump coatings	2006
Alcotec		Belgium	Pump, valve and tank repair	2006
Weir Engineering Services		UK	Pipe work internals	2006
Weir Engineering Services		UK	Pipe work internals	2006

# RB 300 - Case Histories



Contractor	Customer	Location	Description	Date
Weir Engineering Services		UK	Pipe work internals	2006
Weir Engineering Services		UK	Pipe work internals	2006
Finclean SKJ	Chevron Texaco	UK	Vessel internal lining	2006
Weir Engineering Services		UK	Pipe work internals	2006
Weir Engineering Services		UK	Pipe work internals	2006
Weir Engineering Services		UK	Pipe work internals	2006
Market SAS		France	Acid bund lining	2006
Market SAS		France	Internal tank lining	2006
Market SAS		France	Stainless steel tank lining	2006
Repair Protection & Maintenance		UK	Internal vessel lining	2006
Steadvale Air Systems		UK	Compressor sump	2006
Weir Engineering Services		UK	Pipe work internals	2006
GBT Benelux		Belgium	Tank and pump lining	2006
GBT Benelux		Belgium	Tank and pump lining	2006
Weir Engineering Services		UK	Pipe work internals	2006

# RB 300 - Case Histories



Contractor	Customer	Location	Description	Date
Weir Engineering Services		UK	Pipe work internals	2006
GBT Benelux		Belgium	Tank and pump lining	2006
Weir Engineering Services		UK	Pipe work internals	2006
Finclean SKJ	Chevron Texaco	UK	Vessel internal lining	2006
Gemini Corrosion Services	BP Exploration	UK	Internal tank lining	2006
Steadvale Air Systems		UK	Compressor sump	2006
Gemini Corrosion Services	Talisman Energy	UK	Internal tank lining	2006
Repair Protection & Maintenance		UK	Internal tank lining	2006
Market SAS		France	Internal tank lining	2006
Salamis	Talisman Energy	UK	Internal tank lining	2006
Hertel (UK)	BP Exploration	UK	Internal tank lining	2006
Hertel (UK)	BP Exploration	UK	Internal tank lining	2006
Weir Engineering Services		UK	Pipe work internals	2006
Weir Engineering Services		UK	Pipe work internals	2006
Materials Enhancement	British Sugar	UK	Pipe work internals	2006

# RB 300 - Case Histories



Contractor	Customer	Location	Description	Date
US Marine & Industrial Pump Repair		UK	Pump repair	2006
Meldan Fabrications	Chevron Texaco	UK	Internal tank lining	2006
Salamis	Talisman Energy	UK	Internal tank lining	2006
Weir Engineering Services		UK	Pipe work internals	2006
Market SAS		France	Internal tank lining	2006
GCG Shotblasting Services	Talisman Energy	UK	Internal tank lining	2006
Weir Engineering Services		UK	Pipe work internals	2006
Weir Engineering Services		UK	Pipe work internals	2006
Weir Engineering Services		UK	Pipe work internals	2006
Weir Engineering Services		UK	Pipe work internals	2006
Wardle (Painters)	Chevron Texaco	UK	Internal tank lining	2006
Hertel (UK)	BP Exploration	UK	Internal tank lining	2006
W & D Ross	BP Exploration	UK	Internal tank lining	2006
PCiS		UK	Concrete bund	2006
Weir Engineering Services		UK	Pipe work internals	2006
Wardle (Painters)	Chevron Texaco	UK	Pipe work internals	2006



# RB 300 - Case Histories



Contractor	Customer	Location	Description	Date
Repair Protection & Maintenance		UK	Internal tank lining	2006
Weir Engineering Services		UK	Pipe work internals	2006
Weir Engineering Services		UK	Pipe work internals	2006
Salamis	Talisman Energy	UK	Internal vessel lining	2006
Salamis	Talisman Energy	UK	Vessel - tank internals	2006
Weir Engineering Services		UK	Pipe work internals	2006
Weir Engineering Services		UK	Pipe work internals	2006
Weir Engineering Services		UK	Pipe work internals	2006
Finclean SKJ	TOTAL	UK	Vessel internal lining	2006
Repair Protection & Maintenance		UK	Pipe and tank internals	2006
Salamis	Talisman Energy	UK	Internal tank lining	2006
Salamis		UK	Internal tank lining	2006
Steadvale Air Systems		UK	Compressor sump	2006
Weir Engineering Services		UK	Pipe work internals	2006
Weir Engineering Services		UK	Pipe work internals	2006

# RB 300 - Case Histories



Contractor	Customer	Location	Description	Date
Weir Engineering Services		UK	Pipe work internals	2006
Steadvale Air Systems		UK	Compressor sump	2006
Weir Engineering Services		UK	Pipe work internals	2006
Weir Engineering Services		UK	Pipe work internals	2006
Weir Engineering Services		UK	Pipe work internals	2006
Meldan Fabrications	ConocoPhillips	UK	Internal tank lining	2005
Meldan Fabrications	TOTAL	UK	Internal tank lining	2005
Hertel (UK)	BP Exploration	UK	Internal tank lining	2005
Weir Engineering Services		UK	Pipe work internals	2005
Weir Engineering Services		UK	Pipe work internals	2005
Repair Protection & Maintenance		UK	Pipe work internals	2005
Forblast	BP Exploration	UK	Vessel internal lining	2005
Weir Engineering Services		UK	Pipe work internals	2005
Repair Protection & Maintenance		UK	Pipe work	2005
Repair Protection & Maintenance		UK	Vessel internal lining	2005

# RB 300 - Case Histories



Contractor	Customer	Location	Description	Date
Weir Engineering Services	EDF Energy	UK	Pipe work internals	2005
Repair Protection & Maintenance		UK	Pipe work internals	2005
Weir Engineering Services	EDF Energy	UK	Pipe work internals	2005
Weir Engineering Services	EDF Energy	UK	Pipe work internals	2005
Finclean SKJ	TOTAL	UK	Vessel internal lining	2005
Weir Engineering Services		UK	Pipe work internals	2005
Weir Engineering Services		UK	Pipe work internals	2005
Weir Engineering Services		UK	Pipe work internals	2005
Repair Protection & Maintenance		UK	Pressure vessel	2005
Weir Engineering Services		UK	Pipe work internals	2005
Weir Engineering Services		UK	Pipe work internals	2005
Repair Protection & Maintenance		UK	Pipe and tank internals	2005
Weir Engineering Services		UK	Pipe work internals	2005
Weir Engineering Services		UK	Pipe work internals	2005
Marine & Industrial Pump Repair (Gulf)		Bahrain	Internal tank lining	2005

# RB 300 - Case Histories



Contractor	Customer	Location	Description	Date
Marine & Industrial Pump Repair (Gulf)		Bahrain	Internal tank lining	2005
Weir Engineering Services		UK	Pipe work internals	2005
Weir Engineering Services		UK	Pipe work internals	2005
Repair Protection & Maintenance		UK	Pipe and tank internals	2005
Repair Protection & Maintenance		UK	Pipe and tank internals	2005
Weir Engineering Services		UK	Pipe work internals	2005
Weir Engineering Services		UK	Pipe work internals	2005
Weir Engineering Services		UK	Pipe work internals	2005
Ilung C & P Company		Korea	Tanks and structures	2005
Weir Engineering Services		UK	Pipe work internals	2005
Weir Engineering Services		UK	Pipe work internals	2005
Weir Engineering Services		UK	Pipe work internals	2005
Weir Engineering Services		UK	Pipe work internals	2005
Weir Engineering Services		UK	Pipe work internals	2005
Weir Engineering Services		UK	Internal pipe work	2005

# RB 300 - Case Histories




Contractor	Customer	Location	Description	Date
Weir Engineering Services		UK	Pipe work internals	2005
Weir Engineering Services		UK	Pipe work internals	2005
KBR Construction	ConocoPhillips	UK	Internal tank lining	2005
Ilsung C & P Company		Korea	Tanks and structures	2005
JR Rubber & Polyurethane Products	ICI	UK	Vessel internal lining	2005
Weir Engineering Services		UK	Pipe work internals	2005
Weir Engineering Services		UK	Pipe work internals	2005
Weir Engineering Services		UK	Pipe work internals	2005
Weir Engineering Services		UK	Pipe work internals	2005
Market SAS		France	Internal tank lining	2005
Weir Engineering Services		UK	Pipe work internals	2005
Weir Engineering Services		UK	Pipe work internals	2005
Weir Engineering Services		UK	Pipe work internals	2005
Weir Engineering Services		UK	Pipe work internals	2005
PCiS		UK	Acid bund lining	2005

# RB 300 - Case Histories



Contractor	Customer	Location	Description	Date
Weir Engineering Services		UK	Pipe work internals	2005
Weir Engineering Services		UK	Pipe work internals	2005
Kemco Bulgaria		Bulgaria	Internal tank lining	2005
Weir Engineering Services		UK	Pipe work internals	2005
Marine & Industrial Pump Repair (Gulf)		Bahrain	Internal tank lining	2005
Hertel (UK)	BP Exploration	UK	Pressure vessel	2005
Repair Protection & Maintenance		UK	Pipe and tank internals	2005
Hertel (UK)	BP Exploration	UK	Acid bund lining	2005
Acorn Water		UK	External stainless steel plate for reactor vessel	2005
Acorn Water		UK	External stainless steel plate for reactor vessel	2005
US Marine & Industrial Pump Repair		UK	Pump coatings	2005
Sprayglass International		UK	Pipe and tank internals	2005
Weir Engineering Services		UK	Pipe work internals	2005
Advanced Coating Technology		France	Internal tank lining	2005

# RB 300 - Case Histories



Contractor	Customer	Location	Description	Date
Market SAS		France	Internal tank lining	2005
Repair Protection & Maintenance		UK	Pipe and tank internals	2005
Weir Engineering Services		UK	Pipe work internals	2005
Weir Engineering Services		UK	Pipe work internals	2005
Weir Engineering Services		UK	Pipe work internals	2005
Weir Engineering Services		UK	Pipe work internals	2005
Ilung C & P Company		Korea	Tanks and structures	2005
Hertel (UK)	BP Exploration	UK	Pressure vessel	2005
Repair Protection & Maintenance		UK	Pipe and tank internals	2005
Weir Engineering Services		UK	Pipe work internals	2005
Weir Engineering Services		UK	Pipe work internals	2005
Salamis		UK	Vessel - tank internals	2005
Repair Protection & Maintenance		UK	Pipe and tank internals	2005
Salamis		UK	Vessel - tank internals	2004
Weir Engineering Services		UK	Pipe work internals	2004

# RB 300 - Case Histories



Contractor	Customer	Location	Description	Date
Weir Engineering Services		UK	Pipe work internals	2004
Repair Protection & Maintenance		UK	Pipe and tank internals	2004
Weir Engineering Services		UK	Pipe work internals	2004
Weir Engineering Services		UK	Pipe work internals	2004
Repair Protection & Maintenance		UK	Pipe and tank internals	2004
Salamis		UK	Vessel - tank internals	2004
Weir Engineering Services		UK	Pipe work internals	2004
Weir Engineering Services		UK	Pipe work internals	2004
Hertel (UK)	BP Exploration	UK	Acid bund lining	2004
Ilsung C & P Company		Korea	Tanks and structures	2004
Ilsung C & P Company		Korea	Tanks and structures	2004
Weir Engineering Services		UK	Internal pipe work	2004
Weir Engineering Services		UK	Pipe work internals	2004
Weir Engineering Services		UK	Pipe work internals	2004
Salamis		UK	Vessel - tank internals	2004



# RB 300 - Case Histories



Contractor	Customer	Location	Description	Date
Repair Protection & Maintenance		UK	Pipe and tank internals	2004
Repair Protection & Maintenance		UK	Pipe and tank internals	2004
Weir Engineering Services		UK	Pipe work internals	2004
Weir Engineering Services		UK	Pipe work internals	2004
Weir Engineering Services		UK	Pipe work internals	2004
Sprayglass International		UK	Pipe and tank internals	2004
Weir Engineering Services		UK	Pipe work internals	2004
Sprayglass International		UK	Pipe and tank internals	2004
Weir Engineering Services		UK	Pipe work internals	2004
Weir Engineering Services		UK	Pipe work internals	2004
Weir Engineering Services		UK	Pipe work internals	2004
Weir Engineering Services		UK	Pipe work internals	2004
Weir Engineering Services		UK	Pipe work internals	2004
Sprayglass International		UK	Pipe and tank internals	2004
Wardle (Painters)	Chevron Texaco	UK	Internal tank lining	2004
Mitsui Babcock	BP Exploration	UK	Water box internals	2004

# RB 300 - Case Histories



Contractor	Customer	Location	Description	Date
Weir Engineering Services		UK	Pipe work internals	2004
Weir Engineering Services		UK	Pipe work internals	2004
Weir Engineering Services		UK	Pipe work internals	2004
Mitsui Babcock		UK	Condenser puddle pipe work	2004
Repair Protection & Maintenance		UK	Pipe and tank internals	2004
Weir Engineering Services		UK	Pipe work internals	2004
Sprayglass International		UK	Pipe and tank internals	2004
Weir Engineering Services		UK	Pipe work internals	2004
Weir Engineering Services		UK	Pipe work internals	2004
Weir Engineering Services		UK	Pipe work internals	2004
Repair Protection & Maintenance		UK	Pipe and tank internals	2004
Weir Engineering Services		UK	Pipe work internals	2004
Weir Engineering Services		UK	Pipe work internals	2004
Repair Protection & Maintenance		UK	Pipe and tank internals	2004

# RB 300 - Case Histories



Contractor	Customer	Location	Description	Date
Mitsui Babcock		UK	Condenser puddle pipe work	2004
Repair Protection & Maintenance		UK	Pipe and tank internals	2004
Repair Protection & Maintenance		UK	Pipe and tank internals	2004
Repair Protection & Maintenance		UK	Pipe and tank internals	2004
Hertel (UK)	BP Exploration	UK	Vessel internal lining	2004
Weir Engineering Services		UK	Pipe work internals	2004
Repair Protection & Maintenance		UK	Pipe and tank internals	2004
Weir Engineering Services		UK	Pipe work internals	2004
Salamis		UK	Pipe work internals	2004
Salamis		UK	Pipe work internals	2004
Repair Protection & Maintenance		UK	Pipe and tank internals	2004
Repair Protection & Maintenance		UK	Pipe and tank internals	2004
Repair Protection & Maintenance		UK	Pipe and tank internals	2004
Repair Protection & Maintenance		UK	Pipe and tank internals	2004

# RB 300 - Case Histories



Contractor	Customer	Location	Description	Date
Repair Protection & Maintenance		UK	Pipe and tank internals	2004
Weir Engineering Services		UK	Pipe work internals	2004
Weir Engineering Services		UK	Pipe work internals	2004
Weir Engineering Services		UK	Pipe work internals	2004
Weir Engineering Services		UK	Pipe work internals	2004
Repair Protection & Maintenance		UK	Pipe and tank internals	2004
Repair Protection & Maintenance		UK	Pipe and tank internals	2004
Repair Protection & Maintenance		UK	Pipe and tank internals	2004
Repair Protection & Maintenance		UK	Pipe and tank internals	2004
Repair Protection & Maintenance		UK	Pipe and tank internals	2004
Repair Protection & Maintenance		UK	Pipe and tank internals	2004
Repair Protection & Maintenance		UK	Pipe and tank internals	2004
Repair Protection & Maintenance		UK	Pipe and tank internals	2004
Kemco Bulgaria		Bulgaria	Internal tank lining - 98% alcohol	2004

# RB 300 - Case Histories



Contractor	Customer	Location	Description	Date
Repair Protection & Maintenance		UK	Pipe and tank internals	2004
Repair Protection & Maintenance		UK	Pipe and tank internals	2004
Repair Protection & Maintenance		UK	Pipe and tank internals	2004
Repair Protection & Maintenance		UK	Pipe and tank internals	2004
Repair Protection & Maintenance		UK	Pipe and tank internals	2004
Kemco Bulgaria		Bulgaria	Internal tank lining	2004
Weir Engineering Services		UK	Pipe work internals	2004
Weir Engineering Services		UK	Pipe work internals	2004
Weir Engineering Services		UK	Pipe work internals	2004
Repair Protection & Maintenance		UK	Pipe and tank internals	2004
Weir Engineering Services		UK	Pipe work internals	2004
Repair Protection & Maintenance		UK	Pipe and tank internals	2004
Weir Engineering Services		UK	Pipe work internals	2004
Gemini Corrosion Services	BP Exploration	UK	Pipe work internals	2004
Alcotec		Belgium	Acid tank lining	2004

# RB 300 - Case Histories



Contractor	Customer	Location	Description	Date
Repair Protection & Maintenance		UK	Pipe and tank internals	2004
Repair Protection & Maintenance		UK	Pipe and tank internals	2004
Cape Industrial Services		UK	Internal tank lining	2004
Repair Protection & Maintenance		UK	Pipe and tank internals	2004
Repair Protection & Maintenance		UK	Pipe and tank internals	2004
Repair Protection & Maintenance		UK	Pipe and tank internals	2004
Weir Engineering Services		UK	Pipe work internals	2004
Weir Engineering Services		UK	Pipe work internals	2004
Weir Engineering Services		UK	Pipe work internals	2004
Weir Engineering Services		UK	Pipe work internals	2004
Ilsung C & P Company		Korea	Tanks and structures	2004
Weir Engineering Services		UK	Pipe work internals	2004
Weir Engineering Services		UK	Pipe work internals	2004
Repair Protection & Maintenance		UK	Pipe and tank internals	2004
Repair Protection & Maintenance		UK	Pipe and tank internals	2004

# RB 300 - Case Histories



Contractor	Customer	Location	Description	Date
Repair Protection & Maintenance		UK	Pipe and tank internals	2004
Weir Engineering Services		UK	Pipe work internals	2004
Weir Engineering Services		UK	Pipe work internals	2004
Weir Engineering Services		UK	Pipe work internals	2004
Weir Engineering Services		UK	Pipe work internals	2004
Repair Protection & Maintenance		UK	Pipe and tank internals	2004
US Marine & Industrial Pump Repair		UK	Pump coatings	2004
Weir Engineering Services		UK	Pipe work internals	2004
Weir Engineering Services		UK	Pipe work internals	2004
Repair Protection & Maintenance		UK	Pipe and tank internals	2004
Weir Engineering Services		UK	Pipe work internals	2004
Weir Engineering Services		UK	Pipe work internals	2004
Repair Protection & Maintenance		UK	Pipe and tank internals	2004
Weir Engineering Services		UK	Pipe work internals	2004
Weir Engineering Services		UK	Pipe work internals	2004

# RB 300 - Case Histories



Contractor	Customer	Location	Description	Date
Weir Engineering Services		UK	Pipe work internals	2004
Weir Engineering Services		UK	Pipe work internals	2004
Weir Engineering Services		UK	Pipe work internals	2004
Weir Engineering Services		UK	Pipe work internals	2004
Weir Engineering Services		UK	Pipe work internals	2004
Anticorrosion Control Services		Dubai	Seperators - internal lining	2004
Weir Engineering Services		UK	Pipe work internals	2004
Weir Engineering Services		UK	Pipe work internals	2004
Weir Engineering Services		UK	Pipe work internals	2004
Weir Engineering Services		UK	Pipe work internals	2004
Weir Engineering Services		UK	Pipe work internals	2004
Weir Engineering Services		UK	Pipe work internals	2004
Alcotec		Belgium	Acid tank lining	2004
Weir Engineering Services		UK	Pipe work internals	2004
Weir Engineering Services		UK	Pipe work internals	2004
Hertel (UK)	BP Exploration	UK	Acid bund lining	2004
Hertel (UK)	BP Exploration	UK	Pressure vessel	2004



# RB 300 - Case Histories



Contractor	Customer	Location	Description	Date
Weir Engineering Services		UK	Pipe work internals	2004
Weir Engineering Services		UK	Pipe work internals	2004
Weir Engineering Services		UK	Pipe work internals	2004
Weir Engineering Services		UK	Pipe work internals	2003
Weir Engineering Services		UK	Pipe work internals	2003
Repair Protection & Maintenance		UK	Pipe and tank internals	2003
Weir Engineering Services		UK	Pipe work internals	2003
Steadvale Air Systems		UK	Compressor sump	2003
Specialist Industrial Coatings		UK	Acid bund lining	2003
Salamis		UK	Vessel - tank internals	2003
Repair Protection & Maintenance		UK	Pipe and tank internals	2003
Salamis		UK	Vessel - tank internals	2003
Sprayglass International		UK	Pipe and tank internals	2003
Sprayglass International		UK	Pipe and tank internals	2003
Repair Protection & Maintenance		UK	Pipe and tank internals	2003

# RB 300 - Case Histories



Contractor	Customer	Location	Description	Date
Cape Industrial Services	British Gas	UK	Vessel internal lining	2003
Wardle (Painters)	TOTAL	UK	Vessel internal lining	2003
Mitsui Babcock		UK	Condenser puddle pipe work	2003
Wardle (Painters)	TOTAL	UK	Vessel internal lining	2003
Palmers	International Power & Mitsui	UK	Dam wall	2003
Sprayglass International		UK	Pipe and tank internals	2003
US Marine & Industrial Pump Repair		UK	Pump coatings	2003
US Marine & Industrial Pump Repair		UK	Pump coatings	2003
Mitsui Babcock		UK	Condenser puddle pipe work	2003
Hertel (UK)	BP Exploration	UK	Pipe work internals	2003
Steadvale Air Systems		UK	Compressor sump	2003
Alcotec		Belgium	Acid tank lining	2003
Repair Protection & Maintenance		UK	Pipe and tank internals	2003
Repair Protection & Maintenance		UK	Pipe and tank internals	2003
Materials Enhancement	British Sugar	UK	Vessel internal lining	2003
Specialist Industrial Coatings		UK	Vessel - tank internals	2003

# RB 300 - Case Histories



Contractor	Customer	Location	Description	Date
Sprayglass International		UK	Pipe and tank internals	2003
Repair Protection & Maintenance		UK	Pipe and tank internals	2003
Repair Protection & Maintenance		UK	Pipe and tank internals	2003
Sprayglass International		UK	Pipe and tank internals	2003
Sprayglass International		UK	Pipe and tank internals	2003
Repair Protection & Maintenance		UK	Pipe and tank internals	2003
Specialist Industrial Coatings		UK	Acid bund lining	2003
Repair Protection & Maintenance		UK	Pipe and tank internals	2003
Repair Protection & Maintenance		UK	Pipe and tank internals	2003
Repair Protection & Maintenance		UK	Pipe and tank internals	2003
Alcotec		Belgium	Acid tank lining	2003
Sprayglass International		UK	Pipe and tank internals	2003
Sprayglass International		UK	Pipe and tank internals	2003
Sprayglass International		UK	Pipe and tank internals	2003
Sprayglass International		UK	Pipe and tank internals	2003
Salamis		UK	Vessel - tank internals	2003

# RB 300 - Case Histories



Contractor	Customer	Location	Description	Date
Salamis		UK	Vessel - tank internals	2003
Salamis		UK	Vessel - tank internals	2003
Salamis		UK	Vessel - tank internals	2003
Sprayglass International		UK	Pipe and tank internals	2003
Sprayglass International		UK	Pipe and tank internals	2003
Repair Protection & Maintenance		UK	Pipe and tank internals	2003
Sprayglass International		UK	Pipe and tank internals	2003
Hertel (UK)	BP Exploration	UK	Deaerator drum - internal lining	2003
Materials Enhancement	British Sugar	UK	Vessel internal lining	2003
Materials Enhancement	British Sugar	UK	Pressure vessel	2003
Sprayglass International		UK	Pipe and tank internals	2003
Salamis		UK	Vessel - tank internals	2003
Hertel (UK)	BP Exploration	UK	Pipe work internals	2003
Sprayglass International		UK	Pipe and tank internals	2003
Sprayglass International		UK	Pipe and tank internals	2003

# RB 300 - Case Histories




Contractor	Customer	Location	Description	Date
Steadvale Air Systems		UK	Compressor sump	2003
Steadvale Air Systems		UK	Compressor sump	2003
Sprayglass International		UK	Pipe and tank internals	2003
US Marine & Industrial Pump Repair		UK	Pump coatings	2003
Sprayglass International		UK	Pipe and tank internals	2003
US Marine & Industrial Pump Repair		UK	Pump coatings	2003
Sprayglass International		UK	Pipe and tank internals	2003
Sprayglass International		UK	Pipe and tank internals	2003
Sprayglass International		UK	Pipe and tank internals	2003
Sprayglass International		UK	Pipe and tank internals	2003
Sprayglass International		UK	Pipe and tank internals	2003
Sprayglass International		UK	Pipe and tank internals	2003
Jack Tighe Coatings		UK	Internal tank lining	2003
Materials Enhancement	British Sugar	UK	Pressure vessel	2003
Jack Tighe Coatings		UK	Internal tank lining	2003
Repair Protection & Maintenance		UK	Pipe and tank internals	2002
Anticorrosion Control Services		Dubai	Seperators - internal lining	2002
US Marine & Industrial Pump Repair		UK	Pump coatings	2002

# RB 300 - Case Histories



Contractor	Customer	Location	Description	Date
US Marine & Industrial Pump Repair		UK	Pump coatings	2002
Anticorrosion Control Services		Dubai	Seperators - internal lining	2002
Repair Protection & Maintenance		UK	Pipe and tank internals	2002
Repair Protection & Maintenance		UK	Pipe and tank internals	2002
Materials Enhancement	British Sugar	UK	Vessel internal lining	2002
Materials Enhancement	British Sugar	UK	Pressure vessel	2002
Salamis		UK	Vessel - tank internals	2002
Salamis		UK	Vessel - tank internals	2002
Steadvale Air Systems		UK	Compressor sump	2002
Salamis		UK	Vessel - tank internals	2002
Salamis		UK	Vessel - tank internals	2002
Salamis		UK	Vessel - tank internals	2002
Salamis	Talisman Energy	UK	Vessel internal lining	2002
Salamis		UK	Vessel - tank internals	2002
Salamis		UK	Vessel - tank internals	2002
Repair Protection & Maintenance		UK	Pipe and tank internals	2002

# RB 300 - Case Histories



Contractor	Customer	Location	Description	Date
Mitsui Babcock		UK	Condenser puddle pipe work	2002
Anticorrosion Control Services		Dubai	Seperators - internal lining	2002
Anticorrosion Control Services		Dubai	Seperators - internal lining	2002
Anticorrosion Control Services		Dubai	Seperators - internal lining	2002
Mitsui Babcock		UK	Water box internals	2002
Repair Protection & Maintenance		UK	Pipe and tank internals	2002
Repair Protection & Maintenance		UK	Pipe and tank internals	2002
Repair Protection & Maintenance		UK	Pipe and tank internals	2002
Repair Protection & Maintenance		UK	Pipe and tank internals	2002
Wardle (Painters)	ConocoPhillips	UK	Internal tank lining	2002
Wardle (Painters)	TOTAL	UK	Vessel internal lining	2002
Steadvale Air Systems		UK	Compressor sump	2002
Repair Protection & Maintenance		UK	Pipe and tank internals	2002
Wardle (Painters)	ConocoPhillips	UK	Internal tank lining	2002

# RB 300 - Case Histories



Contractor	Customer	Location	Description	Date
Wardle (Painters)	TOTAL	UK	Vessel internal lining	2002
Hertel (UK)	BP Exploration	UK	Acid bund lining	2002
Hertel (UK)	BP Exploration	UK	Pipe work internals	2002
Hertel (UK)	BP Exploration	UK	Gas tank externals	2002
Kemco Bulgaria		Bulgaria	Internal tank lining	2002
Alcotec		Belgium	Acid tank lining	2002
Alcotec		Belgium	Acid tank lining	2002
Alcotec		Belgium	Acid tank lining	2002
Steadvale Air Systems		UK	Compressor sump	2002
Aashish Coating Technologies		India	Pump refurbishment	2001
Barrier		UK	Internal tank lining	2001
Hertel (UK)	BP Exploration	UK	Gas tank externals	2001
Hertel (UK)	BP Exploration	UK	Gas tank externals	2001
Hertel (UK)	BP Exploration	UK	Acid bund lining	2001
Hertel (UK)	BP Exploration	UK	Acid bund lining	2001
Hertel (UK)	BP Exploration	UK	Gas tank externals	2001
Hertel (UK)	BP Exploration	UK	Pressure vessel	2001
Repair Protection & Maintenance		UK	Pipe and tank internals	2001



# RB 300 - Case Histories



Contractor	Customer	Location	Description	Date
Barrier		UK	Internal tank lining	2001
US Marine & Industrial Pump Repair		UK	Pump coatings	2001
Steadvale Air Systems		UK	Compressor sump	2001
Repair Protection & Maintenance		UK	Pipe and tank internals	2001
US Marine & Industrial Pump Repair		UK	Pump coatings	2001
US Marine & Industrial Pump Repair		UK	Pump coatings	2001
Kemco Bulgaria		Bulgaria	Internal tank lining	2001
Repair Protection & Maintenance		UK	Pipe and tank internals	2001
Repair Protection & Maintenance		UK	Pipe and tank internals	2001
Bei-Hai Marine Engineering		Singapore	Seperators - internal lining	2001
Sprayglass International		UK	Pipe and tank internals	2001
Sprayglass International		UK	Pipe and tank internals	2001
Barrier		UK	Internal tank lining	2001
BP International	BP Exploration	UK	Internal tank lining	2001
GE Caledonian		UK	Acid bund lining	2001
Kemco Bulgaria		Bulgaria	Internal tank lining - 98% alcohol	2001

# RB 300 - Case Histories



Contractor	Customer	Location	Description	Date
BP International	BP Exploration	UK	Internal tank lining	2001
Kemco Bulgaria		Bulgaria	Internal tank lining - 98% alcohol	2001
Steadvale Air Systems		UK	Compressor sump	2001
Bei-Hai Marine Engineering		Singapore	Seperators - internal lining	2001
US Marine & Industrial Pump Repair		UK	Pump coatings	2001
US Marine & Industrial Pump Repair		UK	Pump coatings	2001
Steadvale Air Systems		UK	Compressor sump	2001
Wood Group		UK	Internal tank lining	2000
Steadvale Air Systems		UK	Compressor sump	2000
US Marine & Industrial Pump Repair		UK	Pump coatings	2000
US Marine & Industrial Pump Repair		UK	Pump coatings	2000
Steadvale Air Systems		UK	Compressor sump	2000
US Marine & Industrial Pump Repair		UK	Pump coatings	2000
US Marine & Industrial Pump Repair		UK	Pump coatings	2000
Aashish Coating Technologies		India	Acid bund lining	2000
Steadvale Air Systems		UK	Compressor sump	2000
US Marine & Industrial Pump Repair		UK	Pump coatings	2000
US Marine & Industrial Pump Repair		UK	Pump coatings	2000
Aashish Coating Technologies		India	Internal tank lining	2000

# RB 300 - Case Histories



Contractor	Customer	Location	Description	Date
Steadvale Air Systems		UK	Compressor sump	2000
Steadvale Air Systems		UK	Compressor sump	2000
Aashish Coating Technologies		India	Tanks and structures	1999
Steadvale Air Systems		UK	Compressor sump	1999
Steadvale Air Systems		UK	Compressor sump	1999
Steadvale Air Systems		UK	Compressor sump	1999
Bei-Hai Marine Engineering		Singapore	Seperators - internal lining	1999
Bei-Hai Marine Engineering		Singapore	Offshore seperators	1999
Bei-Hai Marine Engineering		Singapore	Internal tank lining	1999
Kemco Bulgaria		Bulgaria	Internal tank lining - 98% alcohol	1999
Bei-Hai Marine Engineering		Singapore	Seperators - internal lining	1999
Bei-Hai Marine Engineering		Singapore	Seperators - internal lining	1999
Bei-Hai Marine Engineering		Singapore	Internal tank lining	1999
Bei-Hai Marine Engineering		Singapore	Internal tank lining	1999

# RB 300 - Case Histories



Contractor	Customer	Location	Description	Date
Bei-Hai Marine Engineering		Singapore	Offshore seperators	1999
Bei-Hai Marine Engineering		Singapore	Offshore seperators	1999
Aashish Coating Technologies		India	Tanks and structures	1998
Bei-Hai Marine Engineering		Singapore	Seperators - internal lining	1998
Bei-Hai Marine Engineering		Singapore	Seperators - internal lining	1998
Aashish Coating Technologies		India	Pump refurbishment	1998
Aashish Coating Technologies		India	Tanks and structures	1998
Aashish Coating Technologies		India	Internal tank lining	1998
Bei-Hai Marine Engineering		Singapore	Seperators - internal lining	1998
Bei-Hai Marine Engineering		Singapore	Seperators - internal lining	1998
Bei-Hai Marine Engineering		Singapore	Seperators - internal lining	1998
Bei-Hai Marine Engineering		Singapore	Seperators - internal lining	1998
Kemco Bulgaria		Bulgaria	Internal tank lining - 98% alcohol	1998
Kemco Bulgaria		Bulgaria	Internal tank lining - 98% alcohol	1998

# RB 300 - Case Histories



Contractor	Customer	Location	Description	Date
Kemco Bulgaria		Bulgaria	Internal tank lining - 98% alcohol	1998
Bei-Hai Marine Engineering		Singapore	Seperators - internal lining	1997
Bei-Hai Marine Engineering		Singapore	Seperators - internal lining	1997
Bei-Hai Marine Engineering		Singapore	Seperators - internal lining	1997
Aashish Coating Technologies		India	Pump refurbishment	1997
Bei-Hai Marine Engineering		Singapore	Seperators - internal lining	1997
Bei-Hai Marine Engineering		Singapore	Seperators - internal lining	1997
Aashish Coating Technologies		India	Acid bund lining	1997
Aashish Coating Technologies		India	Pump refurbishment	1997
Aashish Coating Technologies		India	Tanks and structures	1997
Aashish Coating Technologies		India	Internal tank lining	1997
Bei-Hai Marine Engineering		Singapore	Seperators - internal lining	1997
Bei-Hai Marine Engineering		Singapore	Seperators - internal lining	1997
Bei-Hai Marine Engineering		Singapore	Seperators - internal lining	1997
Aashish Coating Technologies		India	Tanks and structures	1997

# RB 300 - Case Histories



Contractor	Customer	Location	Description	Date
Aashish Coating Technologies		India	Internal tank lining	1997
Aashish Coating Technologies		India	Internal tank lining	1997
Aashish Coating Technologies		India	Acid bund lining	1997
Kemco Bulgaria		Bulgaria	Internal tank lining - 98% alcohol	1997
Aashish Coating Technologies		India	Pump refurbishment	1996
Aashish Coating Technologies		India	Tanks and structures	1996